



EPA Region 5 Records Ctr.



298181

Amoco Oil Company

Wood River Refinery
Post Office Box 182
Wood River, Illinois 62095
Manufacturing Department
618 251 2200

September 22, 1981

Mr. M. Paul Schmierbach, Manager
Permit Section, DAPC
Environmental Protection Agency
2200 Churchill Road
Springfield, Illinois 62706

RECEIVED
SEP 23 1981
IEFA-DAPC-SPEID

Dear Sir:

Triennial Safety Relief Valve Report

Pursuant to IPCB Regulation 205 (g)(3)(D), we are enclosing: 1) a list of unregulated safety relief valves in this refinery capable of causing excessive releases and 2) data on the opening of such valves since September 29, 1978.

Our records show that in the three-year period beginning September 30, 1978, there were no openings of relief valves capable of excessive release. As of May 30, 1981, the Crude Distillation Unit, Catalytic Cracking Unit, Catalytic Reforming and Alkylation are currently not in operation.

Yours truly,

G. F. Nauyok
Refinery Manager

CAB/de

Enc.